

CORNER RECORD

Document Number 20160042

City of _____

County of PLACER, California

Brief Legal Description PARCEL B, PARCEL MAP NO. 72410, BOOK 11, PAGE 21 OF PARCEL MAPS

X	

S 32
T 13N
R 8E

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐

Date of Survey 08/17/2016

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NADV88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISHED THE SOUTHEAST CORNER OF PARCEL B FROM FOUND MONUMENTS
FROM BOTH 11/PM/21 AND 7/PM/122. BEARINGS AND DISTANCES BETWEEN FOUND
MONUMENTS MATCHED RECORD.

A description of the physical condition of the monument as found and as set or reset:

SET A 5/8" X 18" IRON PIN WITH PLASTIC CAP MARKED LS 9034

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on AUGUST 24, 2016.

Signed [Signature] P.L.S. or R.C.E. No.: 9034



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined
and filed September 12, 2016.

Signed [Signature] P.L.S. or R.C.E. No.: 6584

Title County Surveyor


County Surveyor's Comment _____




LEGEND:

- FOUND MONUMENT AS NOTED
 - ⊘ SET 5/8" IRON PIN W/ PLASTIC CAP
MARKED LS 9034
 - DIMENSION POINT. NOTHING FOUND OR SET
- (1) RECORD PER 7/PM/122
(2) RECORD PER 11/PM/21

NOTE: ALL BEARINGS AND DISTANCES AS SHOWN HEREON ARE RECORD PER (1) AND (2)



CORNER RECORD



SLOOTEN CONSULTING INC.

SURVEYING & ENGINEERING

4740 NORTHGATE BLVD., SUITE 115
SACRAMENTO, CA 95834

(916)641-7570
(FAX)641-7572

SCALE: 1"=120'

DATE OF SURVEY: 08/17/2016

PAGE 2 OF 2